

UNIVERSITY OF HOUSTON
Campus Facilities Planning Committee
Agenda Item Description Form

1. **Item:** *Campus Fountain Re-painting*
2. **Requesting Department:** *Facilities Management*
3. **Contact Names & Phone Numbers:** *Roger Warner, 3-9671*
4. **Presenter:** *Roger Warner*
5. **Recommendation/Action Requested:** *Approval*
6. **Summary:**

The current condition of the pool bottoms is poor. Existing paint is peeling and faded. Large portions of the pool bottoms are missing paint and the concrete is exposed.

We are also requesting a color change, from blue to black. Black provides a more reflective quality to the water and helps hide debris on the bottom.
7. **Proposed Start Date:** *March 12, 2012*
8. **Supporting Documentation Description:** *Photos of existing conditions of Cullen, Cheyenne and Student Services Plaza fountains.*

UNIVERSITY of **HOUSTON**

FACILITIES MANAGEMENT

Cullen Fountain – Existing Condition



General appearance of the fountain is a blue-green color due to fading and peeling paint.



Majority of the paint has peeled off exposing the concrete bottom.



Close-up of bottom condition.

UNIVERSITY of **HOUSTON**

FACILITIES MANAGEMENT

Cheyenne Fountain – Existing Condition



Paint is peeling from both the fountain base and the pool wall.

Student Services Plaza Fountain



Almost no paint remaining on pool floor or sides.

UNIVERSITY of
HOUSTON

FACILITIES MANAGEMENT

National Pool Paint Color Chart

White	Med. Blue	Aqua
Sky Blue	Black	Royal Blue
Gray		